Osmo Mobile 2 Release Notes

Date:	2018.04.16
Firmware:	v2.2.0.30
DJI GO App iOS:	v3.1.31
DJI GO App Android:	v3.1.30

What´s New?

• Fixed a rare issue causing pitch axis vibration.

Notes:

• If the firmware update fails, restart the Osmo Mobile 2 and the DJI GO App, then try updating again.

http://www.dji.com/osmo-mobile-2

Osmo Mobile 2 Release Notes

Date:	2018.02.07
Firmware:	v2.1.0.20
DJI GO App iOS:	v3.1.27
DJI GO App Android:	v3.1.28

What´s New?

- Fixed an issue causing a reduction in power when the Osmo Mobile 2 is still connected to the power source after it has been fully charged.

Notes:

- If the firmware update fails, restart the Osmo Mobile 2 and the DJI GO App, then try updating again.

http://www.dji.com/osmo-mobile-2