



Battery Station (For TB50) Release Notes

Date:	2018.11.20
DJI Battery Station:	v1.0.0.36
Internal Battery:	v1.0.0.71
DJI Assistant 2 For Battery Station:	v2.0.0

What's New?

- Batteries can now be updated via the Battery Station (in charging status only). Press "Menu" and select "Battery Update".
- Fixed an issue with the overcurrent protection that occasionally caused the fan stalled.
- Fixed an issue in Quick mode where there was no beep when all the batteries were fully charged.
- Optimized the algorithm of the charging time.

Notes:

- DO NOT update the batteries when the Battery Station is in discharging status.
- Ensure that the battery level is more than 30% before updating the battery firmware.
- The batteries can only be updated when the firmware version is lower than the Battery Station's firmware version. A prompt will appear on the Charging page when an update is available.