



DJI Power 1000 Release Notes

Date:	2024.04.23
Firmware Version:	v01.00.05.00

What's New

- Improved compatibility with certain power grids.
- Improved stability when using SDC output to charge the batteries.
- Fixed an issue where solar recharging is occasionally unavailable.
- Fixed some minor bugs.

Notes:

If the update fails, follow the steps for troubleshooting.

1. Disconnect the computer and all connected devices from the power station.
2. Press and hold the power button for more than five seconds to power off the power station, and exit DJI Assistant 2 (Power Series).
3. Press and hold the AC button and the power button simultaneously. Connect the power station to the computer with a USB-C cable.
4. Connect the power station to an AC power outlet when updating the firmware of DJI Power 1000 with a rated voltage of 100 V or 120 V. Make sure to keep it connected during the updating process.
5. Retry updating the firmware to the latest version using DJI Assistant 2 (Power Series).