



## Zenmuse L2 Release Notes

---

Release Date:	2024.04.28
Zenmuse L2 Firmware:	v02.00.0002
Firmware Upgrade Method:	microSD card / Update All in App
Compatible Firmware and Software Required:	M350 RTK Aircraft: v10.00.06.02 M300 RTK Aircraft: v60.00.01.07 DJI RC Plus Remote Controller: v03.02.09.08 DJI Pilot 2 App: v10.0.6.12

---

### What's Fixed

- Fixed an occasional issue: Camera fan error prompts incorrectly.

### Notes:

- Make sure that the aircraft firmware, the remote controller firmware, the L2 firmware, and the DJI Pilot 2 App are all updated to the latest version.



## Zenmuse L2 Release Notes

---

Release Date:	2023.11.27
Zenmuse L2 Firmware:	v01.00.0002
Firmware Upgrade Method:	microSD card / Update All in App
Compatible Firmware and Software Required:	M350 RTK Aircraft: v08.00.00.04 M300 RTK Aircraft: v58.00.00.10 DJI RC Plus Remote Controller: v02.02.05.07 DJI Pilot 2 App: v8.0.0.38

---

### What 's Fixed

- Fixed issue where point cloud noise appeared in the flight route in some scenarios.

### Notes:

- Make sure that the aircraft firmware, the remote controller firmware, the L2 firmware, and the DJI Pilot 2 App are all updated to the latest version.



## Zenmuse L2 Release Notes

---

Release Date:	2023.10.30
Zenmuse L2 Firmware:	v01.00.0001
Firmware Upgrade Method:	microSD card / Update All in App
Compatible Firmware and Software Required:	M350 RTK Aircraft: v08.00.00.03 M300 RTK Aircraft: v58.00.00.09 DJI RC Plus Remote Controller: v02.02.05.07 DJI Pilot 2 App: v8.0.0.38

---

### What's Fixed

- Fixed issue where the AR projection of laser pinpoints showed position deviation.
- Fixed issue of being unable to obtain task quality reports if there were too many files on the microSD card.

### Notes:

- Make sure that the aircraft firmware, the remote controller firmware, the L2 firmware, and the DJI Pilot 2 App are all updated to the latest version.